

Aerospace Products For Down to Earth Comfort®

# Oregon Aero® SoftTop® Headset Cushion

## Installation Instructions

- Remove one of the headband clamp-nut assemblies from one ear cup and slide the original pad off the headset. Remove the connecting wire from the old pad by pulling forward on the wire until it slips out through a small slit in the plastic. Some headset bands have a small tab punched in them to keep the pad in place. If necessary, use a pair of pliers to partially close this tab to make removal easier.
- 2. Carefully work the SoftTop Headset Cushion onto the band. A thin film of vegetable oil or silicone spray on the band will make this task easier.
- 3. Re-attach the ear cup to the headset band.
- 4. Slip the connecting wire into the new pad which has a has a slit like the original pad.

## For Headsets with Extra Wide Headbands

Remove existing headband pad. Position the SoftTop Headset Cushion under the band and fold self gripping hook and loop flaps over the top for a secure fit.

## For Headsets with Very Thin Headbands

Leave the original headband pad along with the wire(sometimes embedded within the pad) in place. Position the new SoftTop Headset Cushion under the headband and fold the self-gripping hook and loop flaps over the top for a secure fit.

## **Special Installation Note**

In some brands of headsets, the cushion is installed using hot-melt glue on the band. If the cushion resists removal, use a sharp knife to cut the the rubber raceway open along the back of the spring cavity (Opposite the side with the wire raceway cavity). After removing the old cushion, remove as much of the glue as you can. Heat from a cigarette lighter can be helpful during this process. Install the new SoftTop Headset Cushion per prior instructions.

### Cleaning

Sponge clean with a mild cleanser intended for woolens and delicate fabrics per manufacturer's instructions. Allow wool to dry completely and re-fluff with a brush to restore original texture.

#### Satisfaction Guarantee

If you are not satisfied with your Oregon Aero product for any reason, you have 30 calendar days to return the product from the date you purchased it for a full refund or exchange. To be eligible, product must be in good condition and include the receipt.

#### Limited Warranty

This product is backed by a limited warranty against defects in manufacture for a period of two years from the date of purchase. In the event we receive the return of this product within the warranty period, and we agree that the product is defective, our sole obligation shall be to replace the product at no charge. We disclaim all other express or implied warranties, including any implied warranty of merchantability or fitness for a particular use. Some states do not permit the limitation of implied warranties, so this information may not apply to you.

SoftTop® is a registered trademark of Oregon Aero, Inc.

PKG-IN-008 Rev. 12202016

Oregon Aero, Inc. 34020 Skyway Drive, Scappoose OR 97056 www.oregonaero.com customerservice@oregonaero.com Phone: 800-888-6910 503-543-7399 Fax: 503-543-4820 Made in the U.S.A.